

VEHICLE INSPECTION REPORT

PF14TYV

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/08/2014

VIN XLRAEL1500L437939

Axle Combi 4x2

Year 2014

Body Style Box Van

Rear Suspension Steel

Mileage 776,242 Km Warranted

MOT Due 31/07/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

COLLECTED AS NON-RUNNER, PROP SHAFT/ARB LINKS/TYRES

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1


OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Bumper Front
Chipped
Multiple Chips



5: Wing nsf
Chipped
Multiple Chips



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



7: Other
N/A
N/A




8: Other
N/A
N/A



9: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



10: Door osf
Scratched
Over 25mm Thru Paint



11: Door osf
Chipped
Edge Chip



12: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK